	Type	L#	Hits	Search Text	DBs	Time Stamp
1	IS&R	L1	1	("6659779").PN.	i	2004/01/25 21:40
2	IS&R	L2	182	(174/50.56).CCLS.		2004/01/25 21:51
3	IS&R	L3	148	(174/50.59).CCLS.		2004/01/25 21:57
4	BRS	L4	75718	(welder welding).ti.		2004/01/25 21:58

	Туре	L#	Hits	Search Text	DBs	Time Stamp
5	BRS	L5	586		USPA T; US-PG PUB; EPO; JPO; DERW ENT	2004/01/25 21:59
6	BRS	L6	101	(welding) and stud and receptacle and shield\$3	USPA T; US-PG PUB; EPO; JPO; DERW ENT	2004/01/25 22:00
7	BRS	L7	3	(welding).ti. and stud and receptacle and shield\$3		2004/01/25 22:05
8	BRS	L8	3133	(welding).ti. and (arc arcing) same shield\$3		2004/01/25 22:06

J

	Type	L#	Hits	Search Text	DBs	Time Stamp
9	BRS	L9	105	(welding).ti. and (arc arcing) same shield\$3 same (enclosure package housing)	USPA T; US-PG PUB; EPO; JPO; DERW ENT	2004/01/25 22:11
10	BRS	L10	3	(welding and portable).ti. and (arc arcing) same (enclosure package housing)	USPA T; US-PG PUB; EPO; JPO; DERW ENT	2004/01/25 22:12
11	BRS	L11	39	(welding and portable).ti. and (arc arcing)	1	2004/01/25 22:24
12	BRS	L12	81196	219/\$4.ccls.	USPA T; US-PG PUB; EPO; JPO; DERW ENT	2004/01/25 22:25

<

	Type	L#	Hits	Search Text	DBs	Time Stamp
13	BRS	L13	0	219/\$4.ccls. and arc adj1 prevention	USPA T; US-PG PUB; EPO; JPO; DERW ENT	2004/01/25 22:26
14	BRS	L16	362	219/\$4.ccls. and arc\$3 same prevent\$3	USPA T; US-PG PUB; EPO; JPO; DERW ENT	2004/01/25 22:27
15	BRS	L17	221	219/\$4.ccls. and arc\$3 near10 prevent\$3		2004/01/25 22:28
16	BRS	L18	100	219/\$4.ccls. and arc\$3 near prevent\$3		2004/01/25 22:28